• First indication of leak

- LP gas penetration under trailer
- Leak is steady and quick
- Borescope inspection revealed <sup>3/18/2018</sup> 2:54 PM water puddle between floor and sheet metal belly when water is on

IMG\_0378 (14)

Borescope inspection revealed <sup>3/18/2018</sup> 3:03 PM water residue between floor and sheet metal belly

•

Borescope inspection revealed 3/18/2018 1:16 PM water puddle between floor and sheet metal belly when water is on



M9 02:1 8102/81/2

Pipe from hot water tank • Water leaking from seal

3/18/2018 1:34 PM



T-fitting off of hot wat leaking

3/18/2018 1:37 PM

•

T-fitting off of hot water tank i leaking