

## CHASSIS POI

### ENGINE

COMPRESSION TEST - OK ALL CYLS BALANCED

ROUGH OFF IDLE - TIMING VACUUM PROBLEM

EXH LEAKS - MANIFOLD & MUFFLERS

ENGINE LEAKS - W/P / FRONT TIMING SEAL, REAR MAIN, V.O.

MOTOR MOUNTS BROKEN INC TRANS MOUNT

LIFTER NOISE

LOOSE TIMING CHAIN

#### ESTIMATE OF CORRECTIONS & RECOMMENDATIONS:

FEL PRO ENGINE SEAL KIT

Replace MOTOR MOUNTS

Replace CAM & LIFTERS

Replace WATER PUMP

Replace DISTRIBUTOR WITH HEI

Replace ING WIRES

Replace PLUGS

Replace THERMOSTAT

ROT OUT OR REPLACE RAD CORE

Replace TIMING CHAIN

Replace MANIFOLDS WITH HEADERS

Replace FUEL LINES PUMPS, AND FILTERS

Replace AIR FILTER

Replace OIL FILTER AND SYNTHETIC OIL

Replace POWER STEERING PUMP & HIGH PRESSURE LINE

Replace ALL BELTS & HOSES.

Replace REAR MAIN SEAL.

INSTALL HEI BOX WITH REV. LIMITER

oil pump?

## TRANSMISSION

FLUID SMELLS OF VARNISH

TRANS OIL PAN DAMAGED.

REAR SEAL SWELLING OIL

COOLANT LINES SEEPING

Aluminum fin- | But cooler not needed

### CORRECTIONS & RECOMMENDATIONS:

DRAIN & FLUSH OLD FLUID

REPLACE FILTER (INTERNAL)

REPLACE OIL PAN

REPLACE REAR SEAL.

REFILL WITH SYNTHETIC

REPLACE COOLANT LINES

### BRAKES:

SPONGE PEDDLE

FRONT TIRE'S LOOSE.

AXEL SEAL'S LEAKING IN REAR

E BRAKE CABLE NON-OP

### CORRECTIONS & RECOMMENDATIONS:

REPLACE CALIPERS (loaded)

PADS & CHECK & REPLACE FRONT BONGS

TURN ROTORS

REPLACE GRASS SEALS

REPLACE REAR SHOCKS

REPLACE REAR SEALS

REPLACE WHEEL CYLS (REAR)

TURN DRUMS

REPLACE E BRAKE CABLE

FLUSH OUT & REPLACE ALL BRAKE FLUID

## TIRES:

WEATHER CHECKED.

REPLACE ALL      Bridgestone / Goodyear

## SUSPENSION:

SHOCKS

LS BELL CRANK BAD

RS SUSPECT

AIR BAGS NON-OP (FRONT)

SWAY BAR BUSHINGS (BAD)

BALL JOINTS OK

OUTER TIEROD ENDS LOOSE

STEERING DAMPER.

## CORRECTIONS & RECOMMENDATIONS

REPLACE SHOCKS

REPLACE BELL CRANK'S

REPLACE TIE ROD ENDS

REPLACE SWAY BAR BUSHINGS

REPLACE FRONT SPRINGS

REPLACE STEERING DAMPER.

ALIGN FRONT END.

## UNDER VEHICLE INSPECTION

MUFFLERS SHOT

PIPES RUSTED THROUGH.

FRONT DIFF SEAL LEAKING

AXEL BORGES & CARRIER BORGES OK

U-JOINTS SUSPECT (BOTH TRANS SEAL & DIFF SEAL LEAK)

## UNDER VEHICAL INSPECT CONT

FUEL LINES E ELECT PUMP WEAR E TEAR

### CORRECTIONS E RECOMENDATIONS:

REPLACE MUFFLERS E PIPES

REPLACE DIFF SEAL.

DRAIN E REFILL DIFF (WITH SHOCK PROOF)

REPLACE U-JOINTS E BAL SHAFT.

ADD HP FUEL PUMP E REPLACE LINES

AXEL SEALS REPLACED WITH BRAKE TUB.

School  
proof.

### HOUSE POI

#### APPLIANCES

REFER MISSING PARTS NON-OP

FURNACE NON-OP

WATER HEATER OK suspect

STOVE OK

OVEN OK

AIR CONDITIONER (RECHARGE)

Carrier - 13.5  
middle size

### CORRECTIONS E RECOMENDATIONS:

REPLACE REFER. WITH RM 2552 2 WAY

REPLACE HEATER 45,000 B.T.U. DUTHERM

REPLACE A/C WITH CARRIER 15000 BTU

## HOUSE CONTINUED,

### ELECTRICAL:

|                   |             |
|-------------------|-------------|
| SHORE POWER CORD. | BAD!        |
| HOUSE BATT'S      | BAD!        |
| CONVERTER         | BAD!        |
| ALL 12 V LIGHTS   | GOOD        |
| BATH LIGHT & FAN  | BAD!        |
| LIGHT IN KITCHEN  | BAD!        |
| A/C DIST PANEL    | SHORTED     |
| GEN               | NEEDS SERV. |
| TOW WIRING        | NON-UP      |

### CORRECTIONS & RECOMMENDATIONS

|                           |                   |
|---------------------------|-------------------|
| REPLACE SHORE POWER CORD  | REPLACED          |
| REPLACE HOUSE BATTERIES   | WITH 2 6VOLT      |
| REPLACE CONVERTER CHARGER |                   |
| REPLACE 2 FURNOS. & FAN   |                   |
| A/C DISTRIBUTION PANEL    | REPAIR            |
| SERVICE GENERATOR         |                   |
| CHANGE OIL & FILTER       |                   |
| ADJUST OUTPUT!            |                   |
| REPAIR TOW WIRING         | WITH PROPER PLUG. |

### PROPANE

|           |         |
|-----------|---------|
| TANK      | OK      |
| REGULATOR | LEAKING |
| HOSES     | OK      |

RECOMMENDATIONS & CORRECTIONS

REPLACE REGULATOR!

# HOUSE COND "

## TANKS & PLUMBING

LEAKS AT PLASTIC PIPES

LEAK AT WATER PUMP.

WATER PUMP WORK

3" VALVE LEAKING

1 1/2" F.W. VALVE TIGHT!

## RECOMMENDATIONS

REPLACE TUBING

REPLACE BOTH VALVES

REPLACE WATER PUMP

## INTERIOR VISUAL

DRIVERS SEAT.

FLOOR BUCKLED 2 PLACES

DRIVERS SIDE MIRROR

WINDSHIELD SEAL BAD.

## CORRECTIONS & RECOMMENDATIONS

REPAIR DS SEAT

REPAIR DS MIRROR (DONE)

WINDSHIELD RESET

REPLACE WINDSHIELD GASKET.

COSTS PARTS & LABOR  
ON CATEGORIES

|                                  | P | R                 |
|----------------------------------|---|-------------------|
| <u>TIRES</u>                     |   |                   |
| Replace ALL 6 MOUNTED & BALANCED |   | 990 <sup>00</sup> |

### SUSPENSION

|                            |                   |                   |
|----------------------------|-------------------|-------------------|
| Replace SHOCKS 4 @ 80.00   | 320               | 360 <sup>00</sup> |
| Replace BELLERANK          | 345               | 120 <sup>00</sup> |
| Replace ROD ENDS 4 @ 21.00 | 84.00             | 120 <sup>00</sup> |
| Replace SWAY BAR BUSH      | 20.00             | 60 <sup>00</sup>  |
| Replace FRONT Springs      | 365 <sup>00</sup> | 360 <sup>00</sup> |
| Replace Steering Damper    | 82 <sup>00</sup>  | 60 <sup>00</sup>  |
| ALIGN FRONT END            | 80.00             |                   |

|       |      |                    |
|-------|------|--------------------|
| PARTS | 1219 | 1160 <sup>00</sup> |
|-------|------|--------------------|

|     |        |  |
|-----|--------|--|
| TAX | 106.66 |  |
|-----|--------|--|

1325.66

LABOR

1160<sup>00</sup>

# 2485.66

### UNDER VEHICLE

DIFF SEAL Replace

40.00

120<sup>00</sup>

STEWART WARNER E/P.

85.00

60<sup>00</sup>

125.00

10.93

135.93

LABOR

140.00

# 315.93

## TRANS

|                | PARTS         | LABOR |
|----------------|---------------|-------|
| FILTER KIT     | 45.00         |       |
| OIL PAN HP.    | 130.00        | 2.0   |
| 12 QTS SCANTAL | <u>108.00</u> |       |
|                | 383.00        |       |
|                | 24.76         |       |
|                | 407.76        |       |
|                | <u>240.00</u> |       |
| TRAN TOTAL     | 647.76        |       |

## BRAKES

|                      |               |     |
|----------------------|---------------|-----|
| FRONT SEALS (2)      | 26.00         |     |
| LOADED COUPEX (2)    | 160.00        |     |
| TURN ROTORS (2)      | 60.00         |     |
| REAR SHOES (2) SET   | 78.00         |     |
| WHEEL CYLS (2)       | 72.00         | 6.0 |
| HARDWARE KIT (1)     | 28.00         |     |
| TURN DRUMS (2)       | 50.00         |     |
| REAR SEALS (2)       | 56.00         |     |
| BRAKE FLUID (QUART)  | 20.00         |     |
| E BRAKE CABLE REPAIR | 38.00         |     |
|                      | <u>588.00</u> |     |
|                      | <u>51.45</u>  |     |
|                      | 639.45        |     |
|                      | <u>720.00</u> |     |
| TOTAL BRAKE JOB      | 1359.45       |     |

INCLUDES BEARING REPAIR  
FRONT & REAR + SEALS.

| <u>MOTOR</u>               | P       | L |
|----------------------------|---------|---|
| ENGINE SEAL GASKET SET     | 140.00  |   |
| MOTOR MOUNTS TRANS MOUNT   | 250.00  |   |
| WATER PUMP                 | 90.00   |   |
| STERRING PUMP.             | 119.00  |   |
| WIRE SET                   | 125.00  |   |
| DISTRUBETOR HEI            | 259.00  |   |
| HEI BOX                    | 239.00  |   |
| CAM & LIFTER SET.          | 339.00  |   |
| TIMING CHAIN DUAL ROLLER   | 120.00  |   |
| PLUGS                      | 24.00   |   |
| OIL FILTER                 | 9.00    |   |
| WATER WETTER & ANTI FREEZE | 25.00   |   |
| OIL                        | 25.00   |   |
| HEADERS                    | 400.00  |   |
| ROT OR REPLACE RAD CORE    | ?       |   |
| MUFFLERS (2)               | 90.00   |   |
| TUBING 20" 2 1/2           | 40.00   |   |
| 2 1/2 HANGERS (4)          | 20.00   |   |
| ALL ENGINE BELTS           | 35.00   |   |
| ALL HOSES (WATER)          | 28.00   |   |
| THERMOSTAT                 | 5.25    |   |
| PARTS TOTAL                | 2432.00 |   |
| TAX                        | 212.80  |   |
|                            | 2644.80 |   |
| 16 HRS @ 120.00            | 1920.00 |   |
|                            | 4564.80 |   |

Appliances      P      L

|        |               |     |
|--------|---------------|-----|
| Refer  | 1400 00       | 240 |
| Heater | 799 00        | 180 |
| A/C    | 732 00        | 240 |
|        | 2931.00       |     |
| TAX    | <u>246.46</u> |     |
|        | 3177.46       |     |
| Labor  | <u>660 00</u> |     |
|        | 3837.46       |     |

ELECTRICAL

|                     |        |        |
|---------------------|--------|--------|
| Replace Power Cord. | 60.00  | 60.00  |
| BATTS 12V           | 240    | 120.00 |
| 6V                  | 240    | 360.00 |
| CONVERTER           | 345.00 | 120.00 |

MISC INTERIOR

|               |       |            |
|---------------|-------|------------|
| Repair SEAT   |       | 120        |
| Repair Mirror |       | 120        |
| Reset Window  | 90.00 | 500        |
|               | 90    | <u>740</u> |