


Pos wire attached to Pos Battery Cable



Shunt Spliced to Negative Battery Cable.  
3 of the 4 meter wires attach to shunt.