

Safety Issue Type: Recalls

December 20 2012 NHTSA Campaign Number: 12V596000

Sofa Components may Contact Electrical Components

If the metal sofa components come in contact with the electrical components, electrical arcing could occur. Arcing may lead to a vehicle fire.

NHTSA Campaign Number 12V596000

Manufacturer Airstream, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 576

Summary

Airstream is recalling certain model year 2008-2013 Interstate motorhomes manufactured August 2007, through December 2012 and equipped with the rear sofa floor plan. The electrical equipment underneath the sofa may come in contact with the seat belt buckle or metal cables from the seat.

Remedy

Airstream will notify owners, and dealers will install a cover over the electrical components, free of charge. The recall is expected to begin by late January 2013. Owners may contact Airstream at 1-877-596-6111.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Affected Products (6)

Vehicle

MAKE	MODEL	YEAR
AIRSTREAM	INTERSTATE	2008-2013

Associated Documents (11)

Owner Notification Letter(Part 577) - Final

RCONL-12V596-8558.pdf 35.961KB

<https://static.nhtsa.gov/odi/rcl/2012/RCONL-12V596-8558.pdf>

Remedy Instructions and TSB

RCRIT-12V596-8558.pdf 4165.878KB

<https://static.nhtsa.gov/odi/rcl/2012/RCRIT-12V596-8558.pdf>

Quarterly Performance Report

RCQPR-12V596-0213.pdf 6.903KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0213.pdf>

Quarterly Performance Report

RCQPR-12V596-0113.pdf 6.902KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0113.pdf>

Recall Acknowledgement

RCAK-12V596-1443.pdf 48.889KB

<https://static.nhtsa.gov/odi/rcl/2012/RCAK-12V596-1443.pdf>

Defect Notice(Part 573)

RCDNN-12V596-4031.pdf 69.004KB

<https://static.nhtsa.gov/odi/rcl/2012/RCDNN-12V596-4031.pdf>

Quarterly Performance Report

RCQPR-12V596-0114.pdf 7.006KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0114.pdf>

Quarterly Performance Report

RCQPR-12V596-0313.pdf 6.917KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0313.pdf>

Quarterly Performance Report

RCQPR-12V596-0413.pdf 6.91KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0413.pdf>

Quarterly Performance Report

RCQPR-12V596-0214.pdf 13.756KB

<https://static.nhtsa.gov/odi/rcl/2012/RCQPR-12V596-0214.pdf>

Manufacturer Notices(to Dealers,etc)

RCMN-12V596-8558.pdf 20.993KB

<https://static.nhtsa.gov/odi/rcl/2012/RCMN-12V596-8558.pdf>